

The outer (red) holes are used for mounting the Sphere any counter or surface. Print this template at 100% (do not scale printing) for the correct spacing of the mounting and cable pass through holes. 1/4" holes are required for the threaded studs to pass through.

Note: 3.00" threaded rods will fit a maximum counter depth of 2.50".

